Mini Bulletin XRX15P
WorkCentre 5135/5150
WorkCentre 56xx '08 MBC
Release 21.120.065.260

Release Date: May 4, 2015   Version 1.0

Software Release Details

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider taking actions as suggested.

Component	Version
System Software	21.120.065.260
Network Controller	061.105.11210
UI	20.014.090
IOT	92.009.004
SIP	25.064.024
Fax	003.010.004
Scanner	4.22 (65/75ppm)
	17.05 (32/55ppm)

Purpose

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as a criticality level of **IMPORTANT**

- Includes fix for glibc (Ghost) vulnerability

Installation Notes

Firmware Release File

Release Install File	21.120.065.260 or greater

The SPAR Software and installation notes are located here:

http://www.support.xerox.com/support/workcentre-5632-5638/file-download/enus.html?contentId=75245

Save the file to a convenient location on your workstation. Unzip the file if necessary.

Technical Support Operations

Read Me First:

If you have a machine at a System Software version lower than 21.120.040.035 please install **XSA_56xx08_Pre-upgradePatch.dlm** included with this software. This must be installed prior to this system upgrade. If your machine is at System Software version 21.120.040.035 or above, you <u>DO NOT</u> need the pre-upgrade patch.

Note: If your machine is alt-booted by Xerox Service to System Software version 21.120.040.035 or above, you <u>DO NOT</u> need the pre-upgrade patch.

Technical Support Operations