

# Mini Bulletin XRX15E

## WorkCentre 57xx Series

### Release 061.132.224.35203



Release Date: January 26, 2015

Version 1.0

#### Software Release Details

**If your software is higher or equal to the versions listed below no action is needed. Otherwise, please review this bulletin and consider taking actions as suggested.**

Component	Version
System Software	061.132.224.35203
Network Controller	061.134.35220
UI	028.071.00043
IOT Pre-Mod Tag Revision	093.073.000
IOT w/Mod Tag 155	095.040.000
SIP	028.080.00026
DADH	025.020.000
Net Controller OS	061.064.33600

#### Purpose

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as a criticality level of **IMPORTANT**

- Includes SSLv3 POODLE (Padding Oracle on Downgraded Legacy Encryption) vulnerability fix (CVE-2014-3566)
- Includes OpenSSL MiTM (Man in the Middle) vulnerability fix (SSL 0.9.8zc)
- Bash Vulnerabilities CVE-2014-6271, CVE-2014-7169, CVE-2014-7186, CVE-2014-7187, CVE-2014-6277 and CVE-2014-6278 have been fixed in this release. Also known as ShellShock.
- SECURITY CVE 2014-3505, 2014-3506, 2014-3507, 2014-3508, 2014-3510  
Device requires Open SSL version updated to 0.9.8zb or higher

## Installation Notes

### Firmware Release File

Release Install File	061.132.224.35203 or greater
----------------------	------------------------------

The SPAR Software is located here: <http://www.support.xerox.com/support/workcentre-5735-5740-5745-5755/file-download/enca.html?contentId=122838>

The SPAR installation notes are located here:  
[https://www.xrxgsn.com/admin/public/3452/WorkCentre\\_5735-Install\\_Instructions.pdf](https://www.xrxgsn.com/admin/public/3452/WorkCentre_5735-Install_Instructions.pdf)

Save the file to a convenient location on your workstation. Unzip the file if necessary.

### Read Me First:

- When upgrading to **61.132.222.03800** or later from any release less than **61.132.222.03800**, pre-upgrade patch **361374v1.dlm** (found in the .zip file) may need to be installed before upgrading to this latest release. The pre-upgrade patch will retain the **Default Scan Template** settings that were made prior to loading **61.132.222.03800**. If you upgrade to **61.132.222.03800** or later without loading the pre-upgrade patch first, the **Default Scan Template** settings will reset back to factory default at which point you will need to manually set the **Default Scan Template** to the desired settings.